



UNUSUAL ACCIDENT **ON RAIL CROSSING:** 

TRAIN IS CUTTING OFF THE TRAILER FROM THE TRUCK

**DRIVER IS AFTER** ACCIDENT GETTING OUT FROM THE CABINE LOOKING FOR THE **MISSING TRAILER** 



## **NO MORE ACCIDENTS ON THIS CROSSING**

AFTER INSTALLATION OF FPD SYSTEM "STOP AHEAD OF CROSSING"

VEHICLE IS WAITING ON ADDED **TRAFFIC LIGHT ABOUT 50 M** AHEAD OF CROSSING BARIER WHILE CROSSING IS GENERATING ACOUSTIC WARNING SIGNAL ABOUT FOR 30 SECONDS.

FIRST, WHEN BARRIERS GO DOWN, THE DEACTIVATED TRAFFIC LIGHT IS LETING THE VEHICLE CONTINUE **TO THE CROSSING** 





С

## FPD SOLUTIONS FOR RAIL CROSSING

THERE ARE FREQUENT ACCIDENTS AT RAIL CROSSINGS WITH FATAL CONSEQUENCES.

THE STANDARD SAFEGUARDS DEVICES ARE NOT SUFFICIENT.

## FPD COMPANY BRINGS NEW SECURITY FEATURES FOR RAILWAY CROSSINGS TRAFFIC:

Vehicle traffic at a certain distance before railway crossing is controlled by additional signaling system.





- Train is approaching to the rail crossing
- FPD lights are stopping the truck 50m far from barriers, which are lowering

- Barriers are down,
- FPD lights are off and the
- Car can move to the barriers





Car stops in front of the barrierTrain is passing the rail crossing

- Train passed the rail crossing
- Red traffic lights are off
- Barriers are lifted
- Car is safely passing the rail crossing

